

3/4" Iron Bar
NW Corner 8-11-4

(Previously recorded as S88 20'06"W 26'19.10' by R.M. Lempman)

7/16" Iron Bar Found
North 1/4 Corner
Section 8 T11N R4W

1309.55'

654.78' N89°13.36"E

654.77'

1-1/4" Iron pipe by Solberg
(26.67' south of corner) is
0.14' west of line.

S00°19'21"E
1323.61'

NW1/4 NW1/4

1261.70'

(1260.74')
N00°22'56"W
1227.74'

E1/2 NE1/4 NW1/4

18.80 Acres
in the

RA 1242.12' by Knowler
S00°24'12"E
1239.79'

RA 1320' by Solberg

W. 2563.40'
N00°21'42"E

655.71' 1311.42'

655.71' S87°23'44"W

Iron Bar set from Knowler's
(now 28') White Oak witness
tree falls 3.00' South & 1.22'
East of (leaning) 1" iron pipe
from survey by Clayton Solberg

○ 3/4" X 30" Iron Bar Set

* Iron Monument Found

⊕ Found Stone Monument

Solberg:

Refers to survey by Clayton Solberg,
Registered Land Surveyor in December, 1978

Knowler:

Refers to survey by Wm. H. Knowler,
Vernon Co. Surveyor, in September, 1884

(No record by Knowler)
1323.61'

(Knowler's survey did not cover the NW1/4)

Knowler = 1319.01'

N85°34'18"E

2629.27'

(Knowler = 1319.01')
1314.63'

West 1/4 placed midway, matches occupational
evidence extending from Section 7.

Bearings are based upon assigning the south line
of the SW1/4 the bearing of N89°26'22"E.

Knowler = 2695.44'
S00°19'21"W 2647.22'

SURVEYOR'S CERTIFICATE

I, F. Curtis Crook, Registered Land Surveyor,
hereby certify that I have complied with State
laws while conducting this survey, and that this
survey map and description is a correct and true
representation thereof, to the best of my know-
ledge and belief.

F. Curtis Crook R.L.S. 1292

8-2-99

(Description Previously Delivered)

SW Corner
Section 8

N89°25'22"E 1317.77' Knowler = 1317.525' (79 Rods, 21-1/4 Links)

SW Corner
SE1/4 SW1/4



Scale: 1" = 300'



property transaction,
EIDE to RADKE
E1/2 NE1/4 NW1/4
Sec 8 T11N R4W
Town of Franklin,
Vernon County, WI

B408RADK

NOV 8 2004

3: m. m.

Extensive bulldozing in S1/4 Corner area;
further complicated by resultant stump pile